

Figure 1





Figure 2c



10/032,168
Probe Mark Inspection Method and Apparatus
Wallack

Sheet 3 of 7




Figure 3




Figure 4




Figure 5




Figure 6





Figure 7




Figure 10




Figure 8



Figure 9